

**SSM 50114 - 2021 F-150 - SYNC 4 - Inoperative Wireless App Projection Feature - App Disabled Message - Built On Or After 29-Apr-2021 And Through 19-May-2021**

Some 2021 F-150 vehicles equipped with SYNC 4 and built on or after 29-Apr-2021 and through 19-May-2021 may exhibit an inoperative Wireless App Projection feature with a Wireless App Projection Disabled message in the touchscreen. This may be due to various parameters within the gateway module (GWM). To correct the condition, complete Customer Satisfaction Program 21B33.

APPLICABLE VEHICLES  
2021 TRUCK: FD P702N F150